

6. The deck slab repair quantities are estimates from a Thermographic Survey. After removing the surface course the Contractor shall verify the quantities and determine the repair locations in the field.

of the Standard Specifications. If not, the cost to make the

Protective Shield satisfy Article 501.03 shall be included

in the pay item "Deck Slab Repair (Full Depth, Type II)".

Structural Repair of Concrete (Depth equal to or less than 5")

Sq. Ft.

Structural Repair of Concrete

(Depth equal to or less than 5")

rjngroup

200 West Front Street Wheaton, IL 60187

REPAIR PLAN 167th STREET OVER 1-57 FAI RTE 57 SECTION 1011.3 I COOK COUNTY STATION 28+71.53 STRUCTURE NO. 016-2125

DATE: 11-06-2007

DRAWN BY JMT CHECKED BY WJV